Oil Field Environmental Incident Summary

	BURLINGTON RESOL BURLINGTON RESOL ON 14-22MBH ACK BUTTE 2015 Time Incider NZIE	IRCES OIL 8	GAS CO	OMPAN OMPAN <i>Facili</i>	NY LP NY LP W e	ell File # lumber: 22 Q		924 SW SW
Submitted By: Lewi	Red	ceived B	y:					
Contact Person: Le	ewis Schoenberger O BOX 51810 IDLAND, TX 79710-18			-				
General Land Use: W	Vell/Facility Site		Affect	ed Med	dium:	Well/Fa	cility	Soil
Oil 1 Brine Other	er n Dike: Yes - On Facili Units Barrels	ty Site Recovered	Mile Mile Units	Rep		to NRC		o nits
Description of Othe	r Released Contamina	ant:						
Inspected: Risk Evaluation: None Areal Extent:	Written Report Rec	eeived:		Clean	i Up C	onclude	ed:	

			-
Potential	Environ	montal	Impacte
i Otelitiai		nentai i	IIIDacis.

None

Action Taken or Planned:

the oil impacted gravel will be collected for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/22/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, remained on location according to the report. NDIC retains oversight.